

Release Note for Vigor2820 Series

Firmware Version: 3.3.4.1

Built Date: September 24, 2010

Applied Models:

**Vigor2820/2820V/Vigor2820n/Vigor2820Vn/Vigor2820VS/
Vigor2820VSn**

- File and Modem Code

(1)For Annex A Model,

- "v2820_v3341_211011_A" is used for modem code 211011(Standard).
- "v2820_v3341_232201_A.*" is used for modem code 232201 (recommended for UK-SEG only).
- "v2820_v3341_211801_A" is used for modem code 211801.
- "v2820_v3341_2121501_A" is used for modem code 2121501.
- "v2820_v3341_2211201_A" is used for modem code 2211201.
- "v2820_v3341_243601_A" is used for modem code 243601.
- "v2820_v3341_243701_A" is used for modem code 243701.
- "v2820_v3341_244001_A" is used for modem code 244001.
- "v2820_v3341_2431301_A" is used for modem code 2431301.

(2)For Annex B Model,

- "v2820_v3341_2111112_B" is used for modem code 2111112. (Standard)
- "v2820_v3341_214702_B" is used for modem code 214702.
- "v2820_v3341_215202_B" is used for modem code 215202.
- "v2820_v3341_2121302_B" is used for modem code 2121302 (recommended for Slovakia only).
- "v2820_v3341_2111312_B" is used for modem code 2111312.
- "v2820_v3341_2111302_B" is used for modem code 2111302 (recommended for Czech only).
- "v2820_v3341_246302_B" is used for modem code 246302.

New Features

- None.

Improvement

- Fixed: Something wrong with IP Bind MAC.
- Fixed: Rebooting problem for Wi-Fi configuration.

Related Information

- Get the document, please visit <http://www.draytek.com.tw/user/PdInfoDetail.php?Id=72>
- Get the new firmware, please visit <http://www.draytek.com.tw/user/SupportDownloads.php>
- Get the customer service support, please visit <http://www.draytek.com.tw/user/ContactHeadquarters.php>
- Get the regulatory compliance information <http://www.draytek.com.tw/user/AboutRegulatory.php>
- Get information for global partners <http://www.draytek.com.tw/user/Globalpartners.php>

Known Issue

- None

Notes

Modifications

- None