

Release Note for VigorPhone 350

Firmware Version: 12202.26.1.05

Built Date: June 10, 2010

Applied Models: VigorPhone 350

VigorPhone enables you to make phone calls through the IP network instead of calling through a tradition local PSTN line.

It is workable with VigorIPPBX series for auto provision capability. To manage various calling purposes, VigorPhone supports multi-sip registration with different accounts (up to 10) and support G.722 codec for promoting voice quality. The simple WEB UI based configuration allows you to operate VigorPhone with ease.

New Features

- Add *ptime* attribute in SIP Session Description Protocol (SDP).
- Allow two different domain accounts set in PhoneBook to dial each other
- Add *rport* parameter in SIP Via header field
- Add WUI languages supporting French and Polish.

Improvement

- Fixed: STUN issue.
- Fixed: Abnormal month display. When “auto” is selected for daylight saving in NTP&Time setting, more than 12 selections (months) will be offered for Start and End Month items.
- Fixed: Wrong display of caller ID in LCM of VigorPhone 350 after performing call transfer.
- Fixed: VigorPhone 350 jitter issue causes bad voice quality.
- Fixed: Ring tone problem. There are three types of default ring tone for choosing.
- Fixed: Incorrect time display for daylight saving.
- Improved: Language correction for Portuguese, Turkish, German and Dutch.
- Improved: VigorPhone has registered to VigorIPPBX 2820. After finishing the registration, the user continues to dial local telephone. When the remote end picks up the phone call, the user stills hears the ringing tone from VigorPhone. Later, VigorIPPBX 2820 sends the re-inviting to the remote end, VigorPhone will response with “destination unreachable”.
- Improved: A problem occurs when many characters are entered in the field of “Registration

Server” and are saved in VigorPhone 350.

Known Issue

- Upgrading VigorPhone 350 to firmware version 12202.26.1.05 will cause device configuration reset to default. Please backup the System Configuration before upgrading to 12202.26.1.05 and restore the file after the device successfully upgraded to 12202.26.1.05.

Notes

- Please upgrade the VigorPhone 350 to 12202.26.1.04 before performing device firmware upgrade to 12202.26.1.05"

Modifications

- None

Bug Lists

- None