Release Note for Vigor120 V2 Series

Firmware Version: 3.2.4
Built Date: November 4, 2009
Applied Models:
Vigor120 V2

- File and Modem Code

  (1)For Annex B Model,

  - "v12x_b_v324" is used for modem code 311112. (Standard)
  - "v12x_b1_v324" is used for modem code 3101212.
  - "v12x_b2_v324" is used for modem code 3101332.
  - "v12x_b3_v324" is used for modem code 311102.
  - "v12x_b4_v324" is used for modem code 346302.

New Features

- Add a new modem code "346302" for Annex B.
- Add a new VPI/VCI=2/40 into Auto Detection table for Norway.

Improvement

- Improved: Some DSL interoperability problems occurred after updating DSL API driver.
- Corrected: "G.Lite" item on WUI for annex A is lost.
- Corrected: PPPoE may be enabled when we set Internet Access on MPoA mode.
- Corrected: VPN pass-through cannot work.

Known Issue

- None

Notes

Modifications

- None