Release Note for Vigor2865 Series

Firmware Version:	4.3.2.1
Release Type:	Normal
Applied Models:	Vigor2865 / Vigor2865ac / Vigor2865Vac/ Vigor2865L / Vigor2865Lac

Vigor2865 Series is a VDSL2/ADSL2+ Security Firewall router integrating a DSL modem which is compatible with variants of ADSL and VDSL, including profile 35b Super Vectoring.

New Features

- None.

Improvement

- Corrected: An issue of system stability and router reboot.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.
- Corrected: An issue of Hardware Acceleration failed to accelerate the WAN to LAN sessions in the routing mode.

File and Modem Code

- "Vigor2865_v4.3.2.1_STD.zip" provides Annex A modem code 8B0F07_8B0701 and 8B2607_8B0B01, and Annex B modem code 8B2607_8B0B02 and 8B2817_8B0812.
- "Vigor2865_v4.3.2.1_MDM1.zip" provides Annex A modem code 8B1117_8B0701 and 8B0F07_8B0701, and Annex B modem code 8B2817_8B0812 and 8B2607_8B0B02. Recommended for Australia.
- "Vigor2865_v4.3.2.1_MDM2.zip" provides Annex A modem code 8D1917_8D0C11 and 8D1507_8D0901, and Annex B modem code 8D1917_8D0C12 and 8B2817_8B0812.
- "Vigor2865_v4.3.2.1_MDM3.zip" provides Annex A modem code 77C717_8D0C11 and 8D1507_8D0901, and Annex B modem code 77C717_8D0C12 and 8B2607_8B0B02.

Known Issue

- None.