Release Note for VigorAP 910C

Firmware Version: 1.1.5.1
Release Date: September 07, 2015
Applied Models:
VigorAP 910C

VigorAP 910C is a ceiling mount Access Point with PoE for offering power supply and support 300Mbps @2.4GHz, and 866Mbps @5GHz (11ac).

New Features

- Support dynamic frequency selection (DFS) channels for wireless 5G.

Improvement

- Improved: Device Name can be displayed on System Status page.
- Improved: A warning message will appear before AP reboots if the HTTP/HTTPS port number is changed.
- Corrected: TR-069 CPE Username and Password were grayed-out.
- Improved: Remove Autoselect for channel selection in **Wireless LAN (2.4GHz/5GHz) >> Universal Repeater**.
- Corrected: Data information (configured in Quick Start Wizard) for VigorAP could not be shown correctly on Access Point List after scanned by **AP Discovery**.
- Improved: VigorAP support parameters related to Central AP Management for VigorACS (based on TR-069).
- Corrected: Traffic Graphs drew by daily and weekly are inconsistent.
- Improved: Modified the warning message as "The Security and Peer MAC Address of index 1 must be set earlier than index 2." while configuring **Wireless LAN>>General Setup** for WLAN 2.4G **AP Bridge-Point to Multi-Point** mode.
- Corrected: Display error for Rx Rate value in **Wireless LAN (2.4G/5GHz)>>Station List**.

Known Issue

- None

Notes

Modifications

- None

Bug Lists

- None