Release Note for VigorSwitch Q2121x

Firmware Version:	2.9.9
Loader Version:	3.5.1
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	VigorSwitch Q2121x

New Features

- None.

Improvement

- Corrected: An issue with syslog format preventing VigorACS from collecting logs correctly.
- Corrected: An issue that writing an empty port description profile in Central Management would not clear the existing settings on the switch.

Known Issue

- None.

Note

- After upgrading the firmware with this version, downgrading to the previous version (e.g., V2.7.x) is not allowed if the boot loader was 2.2.0.
- STP (Spanning Tree Protocol) is enabled by default starting from firmware version 2.9.8, which may result in a slightly longer link-up time for ports.

RD NO: 115_01_23