

Release Note for Vigor2135 Series

Firmware Version:	4.4.1
Release Type:	Normal
Applied Models:	Vigor2135 / Vigor2135Vac / Vigor2135FVac Vigor2135ac / Vigor2135Fac / Vigor2135FV

Vigor2135 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- None.

Improvement

- Improved: Modify the WUI of 2FA verification code input.
- Improved: Support static route session for hardware acceleration.
- Improved: When Mesh Root is enabled, the WAN TCP port number 9608 will be closed.
- Improved: Support WANx First (WAN Interfaces) for DrayDDNS, Dynamic DNS Account.
- Corrected: An issue of connecting to GenieACS.

Note

- None.

Known Issue

- Do not downgrade the firmware of Vigor router to 4.2.1, if subnet 3 and 4 are enabled.