

Release Note for Vigor2927 Series

Firmware Version:	4.4.6.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor2927, Vigor2927ac, Vigor2927Vac, Vigor2927L, Vigor2927Lac, Vigor2927ax, Vigor2927F, Vigor2927L-5G, Vigor2927Lax-5G

Vigor2927 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Corrected: An issue with a router reboot due to the Web GUI.
- Corrected: An issue with a router reboot when receiving a suspicious TCP packet.
- Corrected: An issue where the router rebooted when DNS Filter, URL Filter, Web Content Filter, or Application Enforcement was enabled and TLS 1.3 hybridized Kyber was used.
- Corrected: An issue where the router rebooted when both WCF and DNS Filters were enabled and the Internet connection was unstable or interrupted.

Known Issue

- None.

Note

- IPsec HMAC (MD5) is no longer supported.