

Release Note for VigorSwitch P2100

Firmware Version:	2.9.5
Loader Version:	3.5.2
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	VigorSwitch P2100

New Features

- None.

Improvement

- Corrected: Issues related to TR-069 parameters.
- Corrected: An issue with the CPU usage occupied in some cases.

Known Issue

- Users could not downgrade the firmware below 2.8.x, if the loader version is 3.5.2.